

No.	Grid Ref.	Eastings	Northings	X	Y
1	G	93800	36000	193800	336000
2	G	94100	36000	194100	336000
3	G	94400	36000	194400	336000
4	G	94700	36000	194700	336000
5	G	93500	35700	193500	335700
6	G	93800	35700	193800	335700
7	G	94100	35700	194100	335700
8	G	94400	35700	194400	335700
9	G	94700	35700	194700	335700
10	G	95000	35700	195000	335700
11	G	95300	35700	195300	335700
12	G	95600	35700	195600	335700
13	G	96500	35700	196500	335700
14	G	97400	35700	197400	335700
15	G	93200	35400	193200	335400
16	G	93500	35400	193500	335400
17	G	93800	35400	193800	335400
18	G	94100	35400	194100	335400
19	G	94400	35400	194400	335400
20	G	94700	35400	194700	335400
21	G	95000	35400	195000	335400
22	G	95300	35400	195300	335400
23	G	95600	35400	195600	335400
24	G	95900	35400	195900	335400
25	G	96200	35400	196200	335400
26	G	96500	35400	196500	335400
27	G	96800	35400	196800	335400
28	G	97100	35400	197100	335400
29	G	97400	35400	197400	335400
30	G	92900	35100	192900	335100
31	G	93200	35100	193200	335100
32	G	93500	35100	193500	335100
33	G	93800	35100	193800	335100
34	G	94100	35100	194100	335100
35	G	94400	35100	194400	335100
36	G	94700	35100	194700	335100
37	G	95000	35100	195000	335100
38	G	95300	35100	195300	335100
39	G	95600	35100	195600	335100
40	G	95900	35100	195900	335100
41	G	96200	35100	196200	335100
42	G	96500	35100	196500	335100
43	G	96800	35100	196800	335100
44	G	97100	35100	197100	335100
45	G	92300	34800	192300	334800
46	G	92600	34800	192600	334800

47	G	92900	34800	192900	334800
48	G	93200	34800	193200	334800
49	G	93500	34800	193500	334800
50	G	93800	34800	193800	334800
51	G	94100	34800	194100	334800
52	G	94400	34800	194400	334800
53	G	94700	34800	194700	334800
54	G	95000	34800	195000	334800
55	G	95300	34800	195300	334800
56	G	95600	34800	195600	334800
57	G	95900	34800	195900	334800
58	G	96200	34800	196200	334800
59	G	96500	34800	196500	334800
60	G	96800	34800	196800	334800
61	G	97100	34800	197100	334800
62	G	97400	34800	197400	334800
63	G	97700	34800	197700	334800
64	G	92000	34500	192000	334500
65	G	92300	34500	192300	334500
66	G	92600	34500	192600	334500
67	G	92900	34500	192900	334500
68	G	93200	34500	193200	334500
69	G	93500	34500	193500	334500
70	G	93800	34500	193800	334500
71	G	94100	34500	194100	334500
72	G	94400	34500	194400	334500
73	G	94700	34500	194700	334500
74	G	95000	34500	195000	334500
75	G	95300	34500	195300	334500
76	G	95600	34500	195600	334500
77	G	95900	34500	195900	334500
78	G	96200	34500	196200	334500
79	G	96500	34500	196500	334500
80	G	96800	34500	196800	334500
81	G	97100	34500	197100	334500
82	G	97400	34500	197400	334500
83	G	97700	34500	197700	334500
84	G	98000	34500	198000	334500
85	G	98300	34500	198300	334500
86	G	98600	34500	198600	334500
87	G	98900	34500	198900	334500
88	G	99200	34500	199200	334500
89	G	91700	34200	191700	334200
90	G	92000	34200	192000	334200
91	G	92300	34200	192300	334200
92	G	92600	34200	192600	334200
93	G	92900	34200	192900	334200

94	G	93200	34200	193200	334200
95	G	93500	34200	193500	334200
96	G	93800	34200	193800	334200
97	G	94100	34200	194100	334200
98	G	94400	34200	194400	334200
99	G	94700	34200	194700	334200
100	G	95000	34200	195000	334200
101	G	95300	34200	195300	334200
102	G	95600	34200	195600	334200
103	G	95900	34200	195900	334200
104	G	96200	34200	196200	334200
105	G	96500	34200	196500	334200
106	G	96800	34200	196800	334200
107	G	97100	34200	197100	334200
108	G	97400	34200	197400	334200
109	G	97700	34200	197700	334200
110	G	98000	34200	198000	334200
111	G	98300	34200	198300	334200
112	G	98600	34200	198600	334200
113	G	98900	34200	198900	334200
114	G	99200	34200	199200	334200
115	G	99500	34200	199500	334200
116	G	99800	34200	199800	334200
117	H	100	34200	200100	334200
118	H	400	34200	200400	334200
119	H	700	34200	200700	334200
120	H	1000	34200	201000	334200
121	G	91400	33900	191400	333900
122	G	91700	33900	191700	333900
123	G	92000	33900	192000	333900
124	G	92300	33900	192300	333900
125	G	92600	33900	192600	333900
126	G	92900	33900	192900	333900
127	G	93200	33900	193200	333900
128	G	93500	33900	193500	333900
129	G	93800	33900	193800	333900
130	G	94100	33900	194100	333900
131	G	95000	33900	195000	333900
132	G	95300	33900	195300	333900
133	G	95600	33900	195600	333900
134	G	95900	33900	195900	333900
135	G	96200	33900	196200	333900
136	G	96500	33900	196500	333900
137	G	96800	33900	196800	333900
138	G	97100	33900	197100	333900
139	G	97400	33900	197400	333900
140	G	97700	33900	197700	333900

141	G	98000	33900	198000	333900
142	G	98300	33900	198300	333900
143	G	98600	33900	198600	333900
144	G	98900	33900	198900	333900
145	G	99200	33900	199200	333900
146	G	99500	33900	199500	333900
147	G	99800	33900	199800	333900
148	H	100	33900	200100	333900
149	H	400	33900	200400	333900
150	H	700	33900	200700	333900
151	H	1000	33900	201000	333900
152	G	91100	33600	191100	333600
153	G	91400	33600	191400	333600
154	G	91700	33600	191700	333600
155	G	92000	33600	192000	333600
156	G	92300	33600	192300	333600
157	G	92600	33600	192600	333600
158	G	92900	33600	192900	333600
159	G	93200	33600	193200	333600
160	G	93500	33600	193500	333600
161	G	93800	33600	193800	333600
162	G	94100	33600	194100	333600
163	G	95600	33600	195600	333600
164	G	95900	33600	195900	333600
165	G	96200	33600	196200	333600
166	G	96500	33600	196500	333600
167	G	96800	33600	196800	333600
168	G	97100	33600	197100	333600
169	G	97400	33600	197400	333600
170	G	97700	33600	197700	333600
171	G	98000	33600	198000	333600
172	G	98300	33600	198300	333600
173	G	98600	33600	198600	333600
174	G	98900	33600	198900	333600
175	G	99200	33600	199200	333600
176	G	99500	33600	199500	333600
177	G	99800	33600	199800	333600
178	H	100	33600	200100	333600
179	H	400	33600	200400	333600
180	H	700	33600	200700	333600
181	G	90800	33300	190800	333300
182	G	91100	33300	191100	333300
183	G	91400	33300	191400	333300
184	G	91700	33300	191700	333300
185	G	92000	33300	192000	333300
186	G	92300	33300	192300	333300
187	G	92600	33300	192600	333300

188	G	92900	33300	192900	333300
189	G	93200	33300	193200	333300
190	G	93500	33300	193500	333300
191	G	93800	33300	193800	333300
192	G	94100	33300	194100	333300
193	G	95600	33300	195600	333300
194	G	95900	33300	195900	333300
195	G	96200	33300	196200	333300
196	G	96500	33300	196500	333300
197	G	96800	33300	196800	333300
198	G	97100	33300	197100	333300
199	G	97400	33300	197400	333300
200	G	97700	33300	197700	333300
201	G	98000	33300	198000	333300
202	G	98300	33300	198300	333300
203	G	98600	33300	198600	333300
204	G	98900	33300	198900	333300
205	G	99200	33300	199200	333300
206	G	99500	33300	199500	333300
207	G	99800	33300	199800	333300
208	H	100	33300	200100	333300
209	H	400	33300	200400	333300
210	G	89900	33000	189900	333000
211	G	90200	33000	190200	333000
212	G	90500	33000	190500	333000
213	G	90800	33000	190800	333000
214	G	91100	33000	191100	333000
215	G	91400	33000	191400	333000
216	G	91700	33000	191700	333000
217	G	92000	33000	192000	333000
218	G	92300	33000	192300	333000
219	G	92600	33000	192600	333000
220	G	92900	33000	192900	333000
221	G	93200	33000	193200	333000
222	G	93500	33000	193500	333000
223	G	93800	33000	193800	333000
224	G	94100	33000	194100	333000
225	G	96200	33000	196200	333000
226	G	96500	33000	196500	333000
227	G	96800	33000	196800	333000
228	G	97400	33000	197400	333000
229	G	97700	33000	197700	333000
230	G	98000	33000	198000	333000
231	G	98300	33000	198300	333000
232	G	98600	33000	198600	333000
233	G	98900	33000	198900	333000
234	G	99200	33000	199200	333000

235	G	99500	33000	199500	333000
236	G	99800	33000	199800	333000
237	H	100	33000	200100	333000
238	H	400	33000	200400	333000
239	H	700	33000	200700	333000
240	H	1000	33000	201000	333000
241	H	1300	33000	201300	333000
242	G	90200	32700	190200	332700
243	G	90500	32700	190500	332700
244	G	90800	32700	190800	332700
245	G	91100	32700	191100	332700
246	G	91400	32700	191400	332700
247	G	91700	32700	191700	332700
248	G	92000	32700	192000	332700
249	G	92300	32700	192300	332700
250	G	92600	32700	192600	332700
251	G	92900	32700	192900	332700
252	G	93200	32700	193200	332700
253	G	93500	32700	193500	332700
254	G	93800	32700	193800	332700
255	G	94100	32700	194100	332700
256	G	94400	32700	194400	332700
257	G	97700	32700	197700	332700
258	G	98000	32700	198000	332700
259	G	98300	32700	198300	332700
260	G	98600	32700	198600	332700
261	G	98900	32700	198900	332700
262	G	99200	32700	199200	332700
263	G	99500	32700	199500	332700
264	G	99800	32700	199800	332700
265	H	100	32700	200100	332700
266	H	400	32700	200400	332700
267	H	700	32700	200700	332700
268	H	1000	32700	201000	332700
269	H	1300	32700	201300	332700
270	G	90200	32400	190200	332400
271	G	90500	32400	190500	332400
272	G	90800	32400	190800	332400
273	G	91100	32400	191100	332400
274	G	91400	32400	191400	332400
275	G	91700	32400	191700	332400
276	G	92000	32400	192000	332400
277	G	92300	32400	192300	332400
278	G	92600	32400	192600	332400
279	G	92900	32400	192900	332400
280	G	93200	32400	193200	332400
281	G	93500	32400	193500	332400

282	G	93800	32400	193800	332400
283	G	94100	32400	194100	332400
284	G	94400	32400	194400	332400
285	G	98000	32400	198000	332400
286	G	98300	32400	198300	332400
287	G	98600	32400	198600	332400
288	G	98900	32400	198900	332400
289	G	99200	32400	199200	332400
290	G	99500	32400	199500	332400
291	G	99800	32400	199800	332400
292	H	100	32400	200100	332400
293	H	400	32400	200400	332400
294	H	700	32400	200700	332400
295	H	1000	32400	201000	332400
296	H	1300	32400	201300	332400
297	G	91100	32100	191100	332100
298	G	91400	32100	191400	332100
299	G	91700	32100	191700	332100
300	G	92000	32100	192000	332100
301	G	92300	32100	192300	332100
302	G	92600	32100	192600	332100
303	G	92900	32100	192900	332100
304	G	93200	32100	193200	332100
305	G	93500	32100	193500	332100
306	G	93800	32100	193800	332100
307	G	94100	32100	194100	332100
308	G	94400	32100	194400	332100
309	G	98900	32100	198900	332100
310	G	99200	32100	199200	332100
311	G	99500	32100	199500	332100
312	G	99800	32100	199800	332100
313	H	100	32100	200100	332100
314	H	400	32100	200400	332100
315	H	700	32100	200700	332100
316	H	1000	32100	201000	332100
317	G	91100	31800	191100	331800
318	G	91400	31800	191400	331800
319	G	91700	31800	191700	331800
320	G	92000	31800	192000	331800
321	G	92300	31800	192300	331800
322	G	92600	31800	192600	331800
323	G	92900	31800	192900	331800
324	G	93200	31800	193200	331800
325	G	93500	31800	193500	331800
326	G	93800	31800	193800	331800
327	G	94100	31800	194100	331800
328	G	94400	31800	194400	331800

329	G	94700	31800	194700	331800
330	G	98900	31800	198900	331800
331	G	99200	31800	199200	331800
332	G	99500	31800	199500	331800
333	G	99800	31800	199800	331800
334	H	100	31800	200100	331800
335	H	400	31800	200400	331800
336	H	700	31800	200700	331800
337	H	1000	31800	201000	331800
338	G	90800	31500	190800	331500
339	G	91100	31500	191100	331500
340	G	91400	31500	191400	331500
341	G	91700	31500	191700	331500
342	G	92000	31500	192000	331500
343	G	92300	31500	192300	331500
344	G	92600	31500	192600	331500
345	G	92900	31500	192900	331500
346	G	93200	31500	193200	331500
347	G	93500	31500	193500	331500
348	G	93800	31500	193800	331500
349	G	94100	31500	194100	331500
350	G	94400	31500	194400	331500
351	G	98900	31500	198900	331500
352	G	99200	31500	199200	331500
353	G	99500	31500	199500	331500
354	G	99800	31500	199800	331500
355	H	100	31500	200100	331500
356	H	400	31500	200400	331500
357	H	700	31500	200700	331500
358	H	1000	31500	201000	331500
359	G	93200	31200	193200	331200
360	G	93500	31200	193500	331200
361	G	93800	31200	193800	331200
362	G	94100	31200	194100	331200
363	G	94400	31200	194400	331200
364	G	94700	31200	194700	331200
365	G	99200	31200	199200	331200
366	G	99500	31200	199500	331200
367	G	99800	31200	199800	331200
368	H	100	31200	200100	331200
369	H	400	31200	200400	331200
370	H	700	31200	200700	331200
371	G	92600	30900	192600	330900
372	G	92900	30900	192900	330900
373	G	93200	30900	193200	330900
374	G	93500	30900	193500	330900
375	G	93800	30900	193800	330900

376	G	94100	30900	194100	330900
377	G	94400	30900	194400	330900
378	G	94700	30900	194700	330900
379	G	95000	30900	195000	330900
380	G	95300	30900	195300	330900
381	G	92300	30600	192300	330600
382	G	92600	30600	192600	330600
383	G	92900	30600	192900	330600
384	G	93200	30600	193200	330600
385	G	93500	30600	193500	330600
386	G	93800	30600	193800	330600
387	G	94100	30600	194100	330600
388	G	94400	30600	194400	330600
389	G	94700	30600	194700	330600
390	G	95000	30600	195000	330600
391	G	95300	30600	195300	330600
392	G	92900	30300	192900	330300
393	G	93200	30300	193200	330300
394	G	93500	30300	193500	330300
395	G	93800	30300	193800	330300
396	G	94100	30300	194100	330300
397	G	94400	30300	194400	330300
398	G	94700	30300	194700	330300
399	G	95000	30300	195000	330300
400	G	92900	30000	192900	330000
401	G	93200	30000	193200	330000
402	G	93500	30000	193500	330000
403	G	93800	30000	193800	330000
404	G	94100	30000	194100	330000
405	G	94400	30000	194400	330000
406	G	94700	30000	194700	330000
407	G	95000	30000	195000	330000
408	G	93800	29700	193800	329700
409	G	94100	29700	194100	329700
410	G	94400	29700	194400	329700
411	G	94700	29700	194700	329700
412	G	95000	29700	195000	329700
413	G	93500	29400	193500	329400
414	G	93800	29400	193800	329400